

SEACOMP

END OF LIFE NOTIFICATION (EOL)

<u>PCN NUMBER</u> EOL20001	<u>DATE</u> April 8, 2020
<u>CUSTOMER(S)</u> ALL CUSTOMERS	
<u>PROJECT(S) AFFECTED</u> DT0010-GG, DT028BTFT-PTS1, DT028CTFT-PTS, DT035BTFT-PTS1, DT043TFT-PTS1, PM9690, PM9796, PM9879, PM9879-GG, PM9950, PM9975	
<u>EFFECTIVE DATE / OTHER REFERENCE</u> <ul style="list-style-type: none">IMMEDIATE	

DETAILS

REASON FOR THE TERMINATION

Due to the end of life of the PCAP Driver IC, FT5346.

LAST TIME BUY

May 29, 2020.

REPLACEMENT PRODUCT

Replacement PCAP Driver IC: FT5446. Focaltech indicates backward compatibility with FT5346. SEACOMP recommends that customer verifies backward compatibility with existing product

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at sales@seacomp.com or the sales contact you are working with.

Sincerely,

For and on behalf of SEACOMP



G. Johnson

Director of Engineering

