## SEACOMP

## **PRODUCT CHANGE NOTIFICATION (PCN)**

PCN NUMBER	DATE
PCN20008	October 30, 2020
CUSTOMER(S)	
ALL CUSTOMERS	
PROJECT(S) AFFECTED	
DT043BTFT-PTS1	
EFFECTIVE DATE / OTHER REFERENCE	
• October 30, 2020	
DESCRIPTION OF CHANGE(S)	
REASON FOR THE CHANGE(S)	

The original touch IC, FT5346, was EOL.

BEFORE CHANGE(S)	AFTER CHANGE(S)
1. The touch IC was FT5346	1. The new touch IC is FT5446;
2. Product P/N was DT043BTFT-PTS1	2. The new product P/N is DT043BTFT-PTS2
	Replacement PCAP Driver IC: FT5446. Focaltech indicates backward compatibility with FT5346.
	<ul> <li>SEACOMP recommends that customer verifies backward compatibility with existing product</li> </ul>

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at <u>sales@seacomp.com</u> or the sales contact you are working with.

Sincerely, For and on behalf of SEACOMP

CyJolfnson Director of Engineering



Displaytech



2546 Gateway Road | Carlsbad, California 92009 | +1 760 918 6722 | www.seacomp.com